

**Photo 1 – N123JN Mooney M20K wreckage debris locations on a Google Earth image.**





**Photo 2 - Main wreckage site indicating aft fuselage and propeller.**





**Photo 3 - Propeller**






**Photo 4 - Left wing exhibiting tree strike at outer section.**



**Photo 5 - Vertical and left horizontal stabilizer. (courtesy of FAA)**





**Photo 6 - Cockpit section indicating engine controls and instrument panel. (Courtesy of FAA)**





**Photo 7- Right separated outboard wing near initial impact site.**





**Photo 8 - Engine separated from the wreckage, leaning against a tree at the end of the debris field.**