

Photographs of N117KP
Courtesy of the Federal Aviation Administration Inspector.



Figure 1: Right side of Airplane



Figure 2: Left side of Engine



Figure 3: Belly Damage at the Nose Landing Gear



Figure 4: Belly Damage just aft of the Nose landing gear



Figure 5: Lower Skin "hole" Damaging the Pressure Vessel



Figure 6: Runway Markings

END. Submitted by: Samantha Link