



Photo 1 – View of the front of the airplane at the accident site.



Photo 2 - View of the right side of the empennage.



Photo 3 - View of the left side of the empennage.



Photo 4 - View of the right side of the airplane.



Photo 5 - View of the left side of the airplane.



Photo 6 - View of the propeller.



Photo 7 - View from a nearby runway towards the accident site.



Photo 8 - View of the carburetor bowl with a blue liquid in it.



Photo 9 - View of a magneto reported to have been installed on the accident airplane.




Photo 10 - View of the accident engine mounted on a test stand.



Photo 11 - View of the distributor cap with the separated center tower.