



Figure 1: Airplane fragment in tree



Figure 2: View from initial impact point looking downhill



Figure 3: Initial ground impact point and main wreckage



Figure 4: View of main wreckage looking back over the debris field



Figure 5: Engine and airframe fragments



Figure 6: Impact damage to the left lower wing