



Photo 1 – Fuselage at accident site.



Photo 2 – Left inboard wing section at accident site.



Photo 3 – Right inboard wing section at accident site.



Photo 4 – Left outboard wing section at accident site.



Photo 5 – Right outboard wing section at accident site.



Photo 6 – Vertical stabilizer at accident site.



Photo 7 – Right engine and propeller at accident site.



Photo 8 – Left engine at accident site.