



Photo 1 – N160RW showing Substantial Damage to the Right Wing



Photo 2 – N160RW showing Substantial Damage to the Right Wing



Photo 3 – N961GG Showing damage to the Propeller



Photo 4 – N961GG showing damage to the Wing Tip