



Photo 1 – Left Side View showing Steering Control damage



Photo 2 - Front View showing Frame Damage