



Photo 1 – View of the wreckage as it came to rest. (Photo courtesy of FAA)



Photo 2 – View of the outboard portion of the right upper wing.(Photo courtesy of FAA)




Photo 3 – View of the right wing support strut. (Photo courtesy of FAA)



Photo 4 – View of the right upper rear spar damage. (Photo courtesy of FAA)



Photo 5 – View of the right side of the rudder. (Photo courtesy of FAA)