



**Photo 1 – Metal building frame with airplane in the background**



**Photo 2 – Front of wreckage with field in the background**



**Photo 3 – Damage to aileron control cable**