



Photo 1 – Accident Site



Photo 2 – Lower Right Wing Main Spar