

3/17/2020

Normal preflight, taxied to RWY 10 RUNUP AREA AND PERFORMED RUNUP AT WHICH POINT EVERYTHING FELT NORMAL. TAXIED TO THE RWY AND ON TAKEOFF NOW HAD THE NORMAL LEFT TURNING TENDENCY. AS SOON AS WE LIFT OFF IT BECAME MORE SEVERE, AND WHEN I WENT TO CORRECT, COULDN'T OVERCOME IT AND DECIDED TO ABORT TAKEOFF.

[REDACTED] (CROSSING LIST) [REDACTED]



3/17/2020

I did pre-flight & PIC take off, everything was working ~~properly~~ correctly. During take off the plane started to veer left. I tried to correct the course and then my instructor tried to correct. The instructor then took over and aborted the take off. [REDACTED]