



Powerplants 8 - Exhibit No. 8B - Photo 13. No. 1 engine thrust reverser actuator support assembly broken at forward end.