



Powerplants 8 - Photo 30. Right propeller blades showing damage to leading edge and missing deicing