

PROGRAM: SS317R8B
 LIBRARY: CSRSPB01
 REPORT : 17.6.2

NEW JERSEY TRANSIT RAIL OPERATIONS
 ACCIDENT/INCIDENT DETAIL BY ACC TYPE W/COST
 JANUARY 01 2007 THRU DECEMBER 31 2016
 ACCIDENT-TYPE: OBSTRUCTION

DATE: 01/27/17
 TIME: 07:49 AM
 PAGE: 52

INC NUM / INC DATE / INC TIME	LINE - TRAIN - VEH NBR/ TRACK NAME / GEOG LOCATION / CITY	EQUIP COST/ F TRACK COST/ R OTHER COST/ A TOTAL COST	ACC / CAUSE CODES / ENGINEER NAME / CONDUCTOR NAME / EQUIPMENT - TRACK	ACCIDENT TYPE, PRIMARY CAUSE & CIRCUMSTANCE
200908543S 08/24/09 10:23 AM	NYCP - NJ6332 - NJTR5030 N #3 NYPs TRACK #3 NEW YORK	1200 0 0 1200	09 / E29C THOMAS H OHANLON ROBERT A DANGIOLILLO	OBSTRUCTION. Other body defects, (CAR) (Provide narrative). COACH #5030 ON TRAIN #6332 REPORTEDLY STRUCK PLATFORM LOCATED AT TRACK #3 WHILE ARRIVING NYPs. COACHES #5030 AND #5533 SHOPPED FOR TRUCK INSPECTIONS.
200702096S 02/12/07 03:37 PM	MORR - MN0064 - NJTR6785 N WEST END INT TK#1 WEST END TK#1 MP2.2 JERSEY CITY	250 2000 0 2250	09 / E99C JOHN P CALIA SALVATORE LASPISA	OBSTRUCTION. Other mechanical and electrical failures, (CAR) (Provide narrative). TRAIN #64 EAST AT WEST END INT . TK#1 HAD AIR HOSES ON COACHES #6785-6794 CATCH SWITCH #29B HEATER DUCTWORK.
201506320S 06/02/15 05:14 AM	HOBT - NJXB12 - NJTR6009 Y TRACK #2 HOBOKEN TRACK #2 HOBOKEN	22300 1502 0 23802	09 / H221 ARTHUR S BOSSERT TASHA T WILKINS 06/02/15 - 06/03/15	OBSTRUCTION. Automatic block or interlocking signal displaying a stop indication - failure to comply. *. TRAIN #X B12 PASSED A STOP SIGNAL AND THEN STRUCK THE BUMPING BLOCK LOCATED ON TRACK #2 WHILE ARRIVING HOBOKEN TERMINAL IN THE DEPOT. 1 INJURY.
200901033S 12/02/08 01:48 PM	NEC - NJ3841 - NJTR1340 N S&I #2 MV YARD S&I #2 MORRISVILLE	1500 0 0 1500	09 / H307 ANTHONY PILLITTERI J SEAN T JENNINGS	OBSTRUCTION. Shoving movement, man on or at leading end of movement, failure to control. TRAIN #3841 STRUCK AVAILABLE YELLOW LADDER FOULING TRACK, CAUSING DAMAGE TO COACH #1340.
200701036S 01/14/07 07:20 PM	MMC - NJMMU4 - NJTR1308 Y CAR SHOP TRACK #5 MMC CAR SHOP TK#5 KEARNY	1000 16000 0 17000	09 / H309 MICHAEL P HAREN JUSTIN N ROXAS	OBSTRUCTION. Failure to stretch cars before shoving. JOB #MMU-4 SHOVING EAST 5 COACHES HAD EAST PAIR #1308-1323 BREAKAWAY AND GO THROUGH CLOSED DOOR TRACK #5 ACCOUNT STRETCH NOT DONE WHEN COUPLED.
200702112S 02/18/07 04:52 PM	MMC - NJMM05 - NJTR4021 N WASH HOUSE TRACK #1 MMC WASH HOUSE TK#12 KEARNY	0 6000 0 6000	09 / H310 DAVID M MACKEY ABRAHAM B RUSSELL /NA/ - /NA/	OBSTRUCTION. Failure to couple. CHOCKED ENGINE ROLLED INTO DOOR, WHEN HOSTLERS TRIED TO COUPLE UP TO IT. EQUIPMENT HAD ONE CHOCK WHICH BEGAN TO SLIDE, WHILE HOSTLER INSERTED ANOTHER CHOCK.
201406363S 05/14/14 08:15 PM	NEC - NJ7273 - NJTR4611 N TRACK #2 NYPs TRACK #2 NEW YORK NEW YORK	0 500 0 500	09 / H401 ANTHONY P PASCALE SR BRADFORD T WAGNER	OBSTRUCTION. Failure to stop train in clear. TRAIN #7273 STRUCK THE BUMPING BLOCK WHILE REVERSING INTO TRACK #2 DUE TO MECHANICAL ISSUES AND DAMAGED THE BUMPING BLOCK. NO DAMAGE REPORTED TO #4611.
200707431S 07/08/07 07:41 AM	NEC - NJ7208 - NJTR4625 Y TRACK #2 NY PENN STATION TK#2 NEW YORK	80600 0 0 80600	09 / H599 JOHN J MARTIN ROBERT P CARBONELLO	OBSTRUCTION. Other causes relating to train handling or makeup (Provide narrative). ENGINEER FAILED TO USE PROPER METHODS TO CONTROL AND STOP TRAIN CAUSING TRAIN #7208 TO STRIKE BUMPING BLOCK NY PENN STATION TRACK #2 AND DERAIL ENGINE #4625.

FRA = Y (REPORTABLE DUE TO COST IS GREATER THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 FRA = N (NON-REPORTABLE DUE TO COST IS LESS THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 OTHER (EVENTS THAT DO NOT INVOLVE CONTACT BETWEEN ON-TRACK EQUIPMENT AND ARE NOT CLASSIFIED AS A COLLISION, DERAILMENT, OTHER IMPACTS, FIRE OR VIOLENT RUPTURE, EXPLOSION-DETONATION, OR GRADE CROSSING ACCIDENT.)

PROGRAM: SS317R8B
 LIBRARY: CSRSPB01
 REPORT : 17.6.2

NEW JERSEY TRANSIT RAIL OPERATIONS
 ACCIDENT/INCIDENT DETAIL BY ACC TYPE W/COST
 JANUARY 01 2007 THRU DECEMBER 31 2016
 ACCIDENT-TYPE: OBSTRUCTION

2

DATE: 01/27/17
 TIME: 07:49 AM
 PAGE: 53

INC NUM / INC DATE / INC TIME	LINE - TRAIN - VEH NBR/ TRACK NAME / GEOG LOCATION / CITY	EQUIP COST/ F TRACK COST/ R OTHER COST/ A TOTAL COST	ACC / CAUSE CODES / ENGINEER NAME / CONDUCTOR NAME / EQUIPMENT - TRACK	ACCIDENT TYPE, PRIMARY CAUSE & CIRCUMSTANCE
201001009S 01/04/10 12:42 PM	HOBT - NJ42 - NJTR6025 Y TRACK #8 DEPOT TRACK #8 DEPOT HOBOKEN	16000 0 0 16000	09 / H607 KYLE L BUTLER JOHN DEMAIO 01/09/10 -	OBSTRUCTION. Failure to comply with restricted speed or its equivalent not in connection with a block or interlock YARD CREW #42 STRUCK BUMPING BLOCK WHILE OPERATING EQUIPMENT INTO DEPOT TRACK #8 LOCATED IN HOBOKEN CAUSING DAMAGE TO CAB CAR #6025.
201106349S 06/08/11 02:42 PM	PR - NJ4145 - NJTR1317 Y SINGLE TRACK PRINCETON STATION PRINCETON	46817 6683 0 53500	09 / H607 HOWARD J HOLMES III ROBERT W GIBBS 06/13/11 - 06/13/11	OBSTRUCTION. Failure to comply with restricted speed or its equivalent not in connection with a block or interlock TRAIN #4145 STRUCK THE BUMPER BLOCK IN PRINCETON AND SHOVED IT APPROX. 10 FT AND DERAILED THE B END TRUCK OF #1317. DCS RULES IN EFFECT.
201506317S 05/31/15 05:38 PM	PR - NJ4253 - NJTR1327 N SINGLE PRINCETON STATION PRINCETON	0 1471 0 1471	09 / H607 NORMAN E ALLEN JONATHAN R NORCROSS 06/03/15 - 05/31/15	OBSTRUCTION. Failure to comply with restricted speed or its equivalent not in connection with a block or interlock TRAIN #4253 STRUCK INTO THE BUMPER BLOCK WHILE ARRIVING PRINCETON STATION. ENGINEER REPORTED RAIN AND WHEEL SLIP AS HE APPLIED BRAKES AND
201601027S 12/29/15 01:15 AM	HOBT - NJYH27 - NJTR4509 N B-12 HOBOKEN TRACK B-12 HOBOKEN	0 6000 0 6000	09 / H607 HOWARD DOBSON RYAN S MITCHELL -	OBSTRUCTION. Failure to comply with restricted speed or its equivalent not in connection with a block or interlock YARD CREW #YH-27 WAS OPERATING EAST ON TRACK #B-12 WITH ENGINE #4509 AND STRUCK THE ROLLING OVERHEAD DOOR THAT WAS IN LOWERED POSITION.
200703191S 03/22/07 11:15 PM	RVL - NJYR03 - NJTR4120 N YARD 4 RARITAN TRACK 4 RARITAN	50 0 0 50	09 / H995 LAWRENCE E BRAIN JR MARK A NICOLETTI 03/29/07 - /NA/	OBSTRUCTION. Human Factor - motive power and equipment. MACHINIST PARKED JOHN DEER (GATOR) TOO CLOSE TO TRACK AND IT WAS STRUCK BY YR-03 CREW MOVING EQUIPMENT ON TRACK 4 TO THE PEDISTAL TRACK. PAINT SCRAPED ON COACH 5446.
201102105S 12/27/10 04:55 PM	NJC - NJXN26 - NJTR6046 N TRACK #2 BELMAR (ENROUTE) BELMAR	8160 0 0 8160	09 / M101 H LORRAINE DEPUGH PETER J BOBINTA 02/11/11 -	OBSTRUCTION. Snow, ice, mud, gravel, coal, sand, etc. on track. TRAIN #XN26 REPORTEDLY STRUCK A SNOW MOUND WHILE ENROUTE IN BELMAR CAUSING DAMAGES TO THE STEPS, SAND HOSE AND CUTTING LEVER ON CAB CAR #6046.
201403146S 02/14/14 04:59 PM	MORR - NJ4610 - NJTR4610 N TRACK #1 MILLBURN MILLBURN	500 0 0 500	09 / M101 JOHN W TORRES PAUL T MONTALBANO -	OBSTRUCTION. Snow, ice, mud, gravel, coal, sand, etc. on track. TRAIN #6641 STRUCK SNOW AND ICE ON TRACKS WHILE ENROUTE WEST NEAR MILLBURN CAUSING DAMAGE TO THE F-END MACHINIST BOX ON ENGINE 4610.
200807445S 07/27/08 09:13 PM	NJC - NJ7286 - NJTR4406 N TRACK #2 MONMOUTH PARK OCEANPORT	0 0 0 0	09 / M301 MICHAEL P HAREN JOSEPH E GUGLIELMO -	OBSTRUCTION. Highway user impairment because of drug or alcohol usage (as determined by local authorities, e.g., . TRAIN #7286 STRUCK A VEHICLE 100FT EAST OF PRIVATE CROSSING RESULTING IN MINOR DAMAGE TO THE AUTOMOBILE AND NO REPORTED DAMAGE TO TRAIN.

FRA = Y (REPORTABLE DUE TO COST IS GREATER THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 FRA = N (NON-REPORTABLE DUE TO COST IS LESS THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 OTHER (EVENTS THAT DO NOT INVOLVE CONTACT BETWEEN ON-TRACK EQUIPMENT AND ARE NOT CLASSIFIED AS A COLLISION, DERAILMENT, OTHER IMPACTS, FIRE OR VIOLENT RUPTURE, EXPLOSION-DETONATION, OR GRADE CROSSING ACCIDENT.)

PROGRAM: SS317R8B
 LIBRARY: CSRSPB01
 REPORT : 17.6.2

NEW JERSEY TRANSIT RAIL OPERATIONS
 ACCIDENT/INCIDENT DETAIL BY ACC TYPE W/COST
 JANUARY 01 2016 THRU DECEMBER 31 2016
 ACCIDENT-TYPE: OBSTRUCTION

3

DATE: 01/27/17
 TIME: 07:37 AM
 PAGE: 7

INC NUM / INC DATE / INC TIME	LINE - TRAIN - VEH NBR/ TRACK NAME / GEOG LOCATION / CITY	EQUIP COST/ F TRACK COST/ R OTHER COST/ A TOTAL COST	ACC / CAUSE CODES / ENGINEER NAME / CONDUCTOR NAME / EQUIPMENT - TRACK	ACCIDENT TYPE, PRIMARY CAUSE & CIRCUMSTANCE
201605227S 04/23/16 01:00 AM	PVL - NJ1636 - NJTR6591 N SINGLE WOOD-RIDGE MP 10.4 WOOD-RIDGE	5817 0 0 5817	09 / M402 EFRAIN BONILLA JR JOHN F PARIS -	OBSTRUCTION. Object or equipment on or fouling track (motor vehicle - other than highway-rail crossing). TRAIN # 1636 STRUCK AN OCCUPIED AUTOMOBILE THAT DROVE ONTO SINGLE TRACK NEAR MP10.4 CAUSING DAMAGE TO CAR #6591. DRIVER WAS CHARGED WITH DUI AND T
201608416S 08/09/16 10:10 PM	NEC - NJ6677 - NJTR7274 N TRACK 12 NY PENN STATION	500 0 0 500	09 / M402 LINDA C BARTLETT ZIPPORAH N THOMPSON -	OBSTRUCTION. Object or equipment on or fouling track (motor vehicle - other than highway-rail crossing). AMTRAK COMMISSARY CART BEING OPERATED BY AMARACK ROLLED INTO THE GAP AND STRUCK INTO TRAIN #6677 BOARDING ON TRACK #12 AND SCRATCHED WINDOW ON CA
201609513S 09/29/16 08:38 AM	HOBT - NJ1614 - NJTR6036 Y TRACK #5 HOBOKEN TERMINAL HOBOKEN	6000000 12000 0 6012000	09 / M505 H604 THOMAS J GALLAGHER THOMAS A DOUGAN -	OBSTRUCTION. Cause under active investigation by reporting railroad (Amended report will be forwarded when complete TRAIN #1614 STRUCK THE BUMPING BLOCK AND HOBOKEN TERMINAL WHILE ARRIVING TRACK#5. 358 PEOPLE WERE EVACUATED. CONFIRMED SPEED EXCEEDED MA

 FRA = Y (REPORTABLE DUE TO COST IS GREATER THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 FRA = N (NON-REPORTABLE DUE TO COST IS LESS THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 OTHER (EVENTS THAT DO NOT INVOLVE CONTACT BETWEEN ON-TRACK EQUIPMENT AND ARE NOT CLASSIFIED AS A COLLISION, DERAILMENT,
 OTHER IMPACTS, FIRE OR VIOLENT RUPTURE, EXPLOSION-DETONATION, OR GRADE CROSSING ACCIDENT.)

PROGRAM: SS317R8B
 LIBRARY: CSRSPB01
 REPORT : 17.6.2

NEW JERSEY TRANSIT RAIL OPERATIONS
 ACCIDENT/INCIDENT DETAIL BY ACC TYPE W/COST
 JANUARY 01 2007 THRU DECEMBER 31 2016
 ACCIDENT-TYPE: **DERAILMENT**

4

DATE: 01/27/17
 TIME: 07:49 AM
 PAGE: 4

INC NUM / INC DATE / INC TIME	LINE - TRAIN - VEH NBR/ TRACK NAME / GEOG LOCATION / CITY	EQUIP COST/ F TRACK COST/ R OTHER COST/ A TOTAL COST	ACC / CAUSE CODES / ENGINEER NAME / CONDUCTOR NAME / EQUIPMENT - TRACK	ACCIDENT TYPE, PRIMARY CAUSE & CIRCUMSTANCE

A RESULT OF A PROBLEM WITH				
200705291S 05/05/07 09:25 AM	HOBT - NJYH91 - NJTR4403 Y TRACK #0 HILL YARD TRACK #0 HOBOKEN	27149 1793 0 28942	01 / H017 EDGAR F WOOTEN DESMOND L WOODS -	DERAILMENT. Failure to properly secure engine(s) (railroad employee). JOB #YHU-91 ATTEMPTING TO COUPLE TO ALP44 #4403 ON HILL YD TK#0 FAILED TO CONFIRM HANDBRAKE APPLIED. #4403 ROLLED 70 YDS INTO BUMPING BLOCK AND DERAILED.
201104237S 04/01/11 11:30 PM	NEC - NJ1483 - NJ1483 N Y-13 MV YARD Y-13 MORRISVILLE	4901 0 0 4901	01 / H018 - -	DERAILMENT. Failure to properly secure hand brake on car (s) (railroad employee). CAR INSPECTOR CONDUCTING A BRAKE TEST RELEASED BRAKES CAUSING EQUIPMENT TO ROLL APPROXIMATELY ONE CAR LENGTH AND DERAIL #1483 OVER DERAIL.
200711716S 11/21/07 08:30 AM	BNTN - NJ9131 - NJTR9131 N SUSSEX JUNCTION SUSSEX BRANCH JCT NETCONG	3000 0 0 3000	01 / H020 MICHAEL J STOLTZ CHARLES OSEI-FRIMPON -	DERAILMENT. Failure to apply sufficient number of hand brakes on car(s) (railroad employee). EXTRA SERVICE CREW COUPLED TO 35 STANDING TIE CARS AND SHOVED WEST UNCOUPLING 11 EMPTY CARS AND REMAINING 24 LOADED CARS ROLLED WEST ON THEIR OWN POWER DERAIL.
200903208S 03/29/09 05:29 PM	MMC - NJMMX4 - NJTR7243 Y COACH LEAD MMC COACH LEAD KEARNY	70000 10000 0 80000	01 / H020 DUDSTON M MAY CHARLES P KULDA JR -	DERAILMENT. Failure to apply sufficient number of hand brakes on car(s) (railroad employee). CONSIST ROLLED APPROXIMATELY 3 CAR LENGTHS THROUGH SW #2107 WHILE UNATTENDED WITHOUT SUFFICIENT NUMBER OF HANDBRAKES APPLIED. CREW MMCX4 OPERATED SAME EQUIPMENT.
201205315S 05/23/12 12:10 AM	MMC - NJMM10 - NJTR1413 Y TRACK #5 EAST MMC TRACK #5 EAST KEARNY	16273 0 0 16273	01 / H020 RAYMOND J PEREIRA THOMAS J CRENNAN 08/02/12 -	DERAILMENT. Failure to apply sufficient number of hand brakes on car(s) (railroad employee). MM-10 WITH 7 CARS COUPLED TO MU CARS 1413/1412. HANDBRAKE WAS APPLIED ON 1412 AND A CHOCK ON THE OUTER RAIL OF 1413 EAST TRACK. 1413 DERAILED OVER CHOCK.
201209566S 09/05/12 08:17 PM	GLAD - NJEXTA - NJTR6022 N TRACK #2N GLADSTONE YARD GLADSTONE	3700 0 0 3700	01 / H020 - -	DERAILMENT. Failure to apply sufficient number of hand brakes on car(s) (railroad employee). CAR INSPECTOR EMPLOYEE RELEASED BRAKES FROM CAR #6022 AND EQUIPMENT ROLLED 16 FEET CAUSING DERAILMENT OF THE #4 WHEEL OVER THE EAST END DERAIL ON TRACK #2N.
200706415S 06/28/07 01:45 AM	NEC - NJYMU1 - NJTR1357 N TK #1 LEAD, SW#3 MORRISVILLE YD 1LEAD MORRISVILLE	9388 300 0 9688	01 / H021 RAYMOND J PEREIRA NEAL FEELEY 06/28/07 -	DERAILMENT. Failure to apply hand brakes on car(s) (railroad employee). AIII #1356 ROLLED OUT ON #1 LEAD AND DERAILED ACCOUNT HAND BRAKE NOT APPLIED.
200808496S 08/05/08 02:25 PM	HOBT - NJ5025 - NJTR5025 N ENGINE HOUSE LEAD HOBOKEN ENG HS LEAD HOBOKEN	1048 0 0 1048	01 / H021 DONALD LANE - 08/05/08 -	DERAILMENT. Failure to apply hand brakes on car(s) (railroad employee). COACH #5025 ROLLED APPROXIMATELY 30 FT AND DERAILED ONE WHEEL OF THE NO.4 WHEEL SET OVER PROTECTIVE DERAIL.

 FRA = Y (REPORTABLE DUE TO COST IS GREATER THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT
 FRA = N (NON-REPORTABLE DUE TO COST IS LESS THAN \$ 10700 AS OF 01/01/17 OR \$ 10500 BEFORE OR IS A GRADE CROSSING ACCIDENT)
 OTHER (EVENTS THAT DO NOT INVOLVE CONTACT BETWEEN ON-TRACK EQUIPMENT AND ARE NOT CLASSIFIED AS A COLLISION, DERAILMENT,
 OTHER IMPACTS, FIRE OR VIOLENT RUPTURE, EXPLOSION-DETONATION, OR GRADE CROSSING ACCIDENT.)