



Photo 1 - Overall accident scene. Wreckage is up against building (background). Note ground skid marks.



Photo 2 – Left wing tip separated when wing struck the ground.



Photo 3 - Skid mark created by left wing tip contacting the ground.



Photo 4 - Closer view of heavier skid marks.



Photo 5 - Close-up view of main impact point.



Photo 6 - N1095V rests against building.



Photo 7 - Another view of N1095V.



Photo 8 - The detached propeller at main impact point.



Photo 9 - Close-up view of the detached propeller.



Photo 10 - Rear view of N1095V.



Photo 11 - Frontal view of N1095V.