

ENGINE EXAMINATION REPORT				
FILE NUMBER:	16-570	ENGINE S/N:	808287	PAGE 2 of 7

GENERAL INFORMATION				
EXAMINATION		ACCIDENT DATA		
DATE	11/01	/2017	NTSB ACCIDENT #	CEN17FA167
FACILITY	Analy	tical Department	NTSB INVESTIGATOR	John Brannen
ADDRESS	2039	S Broad St	FAA INVESTIGATOR	Unknown
	Mobil	e, AL 36615	ACCIDENT DATE	04/25/2017
			ACCIDENT LOCATION	Huntsville, Texas
ENGINE INFORMATION				
ENGINE POSITION Right				
TOTAL TIME 2,627.4 As of 04/24		/2017		
TIME SOH 381.4 As of 04/24		/2017		
TYPE & TIME SLI Unknown				
BUILD DATE 09/28/1996				
IN SERVICE DATE Unknown				

**Significant logbook information:** The engine was overhauled by Ram Aircraft in Waco, Texas on 10/03/2011. The last 100 hour inspection was performed by Mr. Wes Wright AP2994045IA on 04/24/2017.

## **Report Summary:**

Search Code(s):

The engine was disassembled and examined in the Continental Motors Analytical Department on 11/01/2017 under the supervision of the NTSB Investigator in Charge.

No discrepancies were observed that would have prohibited the production of full rated horse power.

## Disposition of engine following exam:

The engine was released for return to storage at Air Salvage of Dallas in Lancaster, Texas.

ENGINE EXAMINATION REPORT				
FILE NUMBER:	16-570	ENGINE S/N:	808287	PAGE 3 of 7


INSPECTION WITNESSES					
NAME	Phillip Grice	NAME	Greg Eastburn		
ADDRESS	Mobile, Alabama	ADDRESS	Mobile, Alabama		
ORGANIZATION	Continental Motors	ORGANIZATION	Continental Motors		
PHONE		PHONE			
NAME	Lisa Jersild	NAME	John T. Kent		
ADDRESS	Mobile, Alabama	ADDRESS	Mobile, Alabama		
ORGANIZATION	Continental Motors	ORGANIZATION	Continental Motors		
PHONE		PHONE			
NAME	John Brannen	NAME	Rick Roper		

ADDRESS	Chicago, Illinois	ADDRESS	Waco, Texas
ORGANIZATION	NTSB	ORGANIZATION	Ram Aircraft
PHONE		PHONE	

## **EXTERNAL INSPECTION OF ENGINE**













## INTERNAL INSPECTION OF ENGINE







	ENGINE EXAMINATION REPORT				
FILE NUMBER:	16-570	ENGINE S/N:	808287	PAGE 7 of 7	