#### Signal Incidents 08/01/12 to 08/31/12 MP BAC 12.0 - 16.0

13 Total Incidents

### Incident # 5184066 Closed Incident History

Description 08/07/2011 17:05:30 Status Unassigned By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

BA BC OM SUB

TOL ON 5310 013.

Updated 08/07/2011 17:33:53Status ActiveBy Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

Original report was 2 TOLs 5310 013 And 5311 003. Both TOLs showing clear at this time. Storms in area at the time of report.

Updated 08/07/2011 17:34:15 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

A email notification for Chronic asset 3 CKT WE AVALON TO EE DAVIS (3) has been sent to the following:

Donald Hodges
Daniel Zink

Updated 08/07/2011 17:34:15 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

New Asset Added: 3 - 3 CKT WE AVALON TO EE DAVIS

Closed 08/07/2011 19:33:09 Status Closed By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept. Weather

Message#

Responsibility Control Center Responsible Dept. Weather Message# Jumpers N/A Incident Resolved: 08/07/2011 18:00:00

Jumpers N/A

Equipment Type: Other - explain Action Taken: Other - explain Suspected Reason: Other weather

Mtr reports TOLs cleared upon there own. Due to possible heavy rain at the time.

**Operational Checks Performed** 

## Incident # 5197704 Closed Incident History

Description 08/14/2011 23:29:39 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

BALT BC Desk 5310-5311

Old Main Line Davis-Avalon 2310/14 Track Circuits after Q39814

Updated 08/14/2011 23:29:57 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority

Message#

Jumpers N/A

A email notification for Chronic asset 3 CKT WE AVALON TO EE DAVIS (4) has been sent to the following:

Donald Hodges Daniel Zink

Updated 08/14/2011 23:29:57 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

New Asset Added: 3 - 3 CKT WE AVALON TO EE DAVIS

Updated 08/15/2011 01:14:10 Status Escalated By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

call list exhausted, signal supervisor notified and will handle dispatching a mntr.

Closed 08/15/2011 04:35:22 Status Closed By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept. Weather

Message#

Jumpers N/A

Incident Resolved: 08/15/2011 02:33:00

Equipment Type: N/A

Action Taken: Issue cleared before cause identified

Suspected Reason: Other weather

tols have been clear for several hrs. no mntr dispatched

**Operational Checks Performed** 

### Incident # 5199297 Closed Incident History

Description 08/15/2011 15:30:30Status UnassignedBy Travis Hudson - SignalsInc Type Track circuit (TOL)Asset Status DtlPriority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Balt

Old Main Line Sub

BC Disp

Track light - 5310 013

Updated 08/15/2011 15:30:35 Status Unassigned By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

A email notification for Chronic asset 13 CKT EE DAVIS TO WE AVALON (3) has been sent to the following:

Donald Hodges Daniel Zink

Updated 08/15/2011 18:50:05 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Mtr is going on the HSL. Reports power off is just an indication, commercial power is ON. 2 TOLs are now at 5310 013 and

5311 003. Second Mtr en route.

Updated 08/15/2011 18:50:48 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

A email notification for Chronic asset 3 CKT WE AVALON TO EE DAVIS (5) has been sent to the following:

Donald Hodges Daniel Zink

Updated 08/15/2011 18:50:48 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

New Asset Added: 3 - 3 CKT WE AVALON TO EE DAVIS

Closed 08/15/2011 23:03:26 Status Closed By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Weather Message# Jumpers N/A

Incident Resolved: 08/15/2011 22:45:00

Equipment Type: N/A

Action Taken: Eqpt tested & fnd working as intended

Suspected Reason: Other weather

mntr found everything coa. all op checks were performed, heavy rains were in the area at the time of the report

Operational Checks Performed

### Incident # 5210673 Closed Incident History

Description 08/21/2011 13:38:30 Status Unassigned By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

BAL CHIEF BC DISPR OM SUB

LOCATION 5310-013

TOL BETWEEN DAVIS AND AVALON, ALSO POWER OFF AT WEST AVALON, LOCATION 5311.

Updated 08/21/2011 13:38:31 Status Unassigned By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

A email notification for Chronic asset 13 CKT EE DAVIS TO WE AVALON (4) has been sent to the following:

Donald Hodges Daniel Zink

Closed 08/21/2011 22:06:59 Status Closed By Robrt Flora - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Weather Message# Jumpers N/A

Incident Resolved: 08/21/2011 22:06:00

Equipment Type: Track

Action Taken: Made other repairs Suspected Reason: Other weather

reset GEO unit, checked amps east and west, working as intendid

Operational Checks Performed

### Incident # 5246571 Closed Incident History

Description 09/08/2011 17:51:41 Status Unassigned By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

BA Chief OM Sub BC Disp

EE Davis 5310 013, track light on by itself

Updated 09/08/2011 17:51:42 Status Unassigned By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Jumpers N/A

A email notification for Chronic asset 13 CKT EE DAVIS TO WE AVALON (4) has been sent to the following:

Donald Hodges Daniel Zink

Updated 09/08/2011 18:22:14 Status Deferred By Travis Hudson - Signals

Inc Type Track circuit (TOL) Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

TOL is showing clear, will continue to monitor.

EXTENDED: MODERATE RAIN CONTINUES OVER THIS AREA OF TRACK. EXPECT NEW RAINFALL OF 1-1.5 INCHES TO CAUSE ADDITIONAL FLASH FLOODING. BE ALERT FOR PONDING WATER AND POSSIBLE WASHOUTS ON TRACK.

Updated 09/08/2011 19:26:51 Status Escalated By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

TOL pumping and on steady now. Supervisor notified. Incident handed over to the supervisor of the territory for further handling.

Closed 09/08/2011 21:00:01 Status Closed By Bernard Watkins - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Weather Message# Jumpers N/A

Incident Resolved: 09/08/2011 20:59:00 Equipment Type: Signal - not bulbs

Action Taken: Adjusted/Cleaned/Repaired/Reset

Suspected Reason: Other weather

adjusted track current due to incliment weather at Daniels Signal

**Operational Checks Performed** 

### Incident # 5323719 Closed Incident History

Description 10/26/2011 06:32:24 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

BALT BC Desk 5310-5311

Old Main Line Davis-Avalon 0615/26 Track Circuit after Q37025

Updated 10/26/2011 06:36:37 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL) Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A Ess spoke with the signal supervisor and he'll handle dispatching a mntr. Supervisor beleives the issue to the power off.

Updated 10/26/2011 06:38:31 Status Deferred By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

.

Updated 10/26/2011 07:54:50 Status Active By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

mntr Tarleton will investigate.

Updated 10/26/2011 10:58:52 Status Active By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

mntr refueled generator at EE Davis. still investigating TOL.

Updated 10/26/2011 12:23:48 Status Transferred By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

mntr broken rail at mp BAC 12.8 south rail, 141 lb, MOW and dispatcher have been ntfd.

Updated 10/26/2011 16:53:55 Status Transferred By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control

Responsibility Con

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

Signal Mtr reports another broken rail MP BAC 12.9. MOW still working in area, Mtr on site waiting to bond rails.

Closed 10/26/2011 17:17:04 Status Closed By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

Incident Resolved: 10/26/2011 17:16:00

Equipment Type: Track

Action Taken: Broken Rail - Repaired/Replaced

Suspected Reason: N/A

Signal Mtr bonded rails and performed operational checks.

Operational Checks Performed

### Incident # 5411876 Closed

**Incident History** 

Description 01/03/2012 03:17:57 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

BALT BC DESK

OLD MAIN LINE SUB

TRACK LIGHT BTWN EE DAVIS AND WE AVALON LOC 5310 013

Updated 01/03/2012 06:34:57 Status Active By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

mntr found a 4 inch pull apart at mp BAC 14.2 on the south rail. mow is in route to make repairs.

Closed 01/03/2012 17:20:00 Status Closed By Travis Hudson - Signals

Inc Type Track circuit (TOL) Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

Incident Resolved: 01/03/2012 10:05:00

Equipment Type: Track

Action Taken: Broken Rail - Repaired/Replaced

Suspected Reason: Track/rail/drainage/surface/fouled ballast

MOW Closed:

Incident Resolved: 01/03/2012 10:05:00

Equipment Type: Joint Bars Action Taken: Repaired

Suspected Reason: Material Failure

Pull apart repaired.

Supervisor notified and reports no bonding needed.

MOW welded joint.

**Operational Checks Performed** 

### Incident # 5440915 Closed Incident History

**Description** 01/21/2012 23:30:15

Status Unassigned

By James Earp - Signals

Inc Type Track circuit (TOL)
Responsibility Control Center

Asset Status Dtl Responsible Dept.

Priority 1 Message#

Jumpers N/A

BALT BC Desk 5310-5311

Old Main Line Davis-Avalon 2320/21 Track Circuit after U83620

**Updated** 01/22/2012 02:08:45

Status Escalated

By James Earp - Signals

Inc Type Track circuit (TOL)
Responsibility Control Center

Asset Status Dtl Responsible Dept. Priority 1 Message#

Jumpers N/A

ESS exhausted call list and notified supervisor Hodges via phone. Will RTL again.

**Updated** 01/22/2012 03:09:00

Status Escalated

By James Earp - Signals

Inc Type Track circuit (TOL)
Responsibility Control Center

Asset Status Dtl Responsible Dept. Priority 1 Message#

Jumpers N/A

Track inspector reports 4" pull-apart @ BAC 13.4, estimates 3 hours to have repaired.

Closed 01/22/2012 08:51:56

Status Closed

By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center

Responsible Dept. Engineering

Message#

Jumpers N/A

Incident Resolved: 01/22/2012 08:51:00

Equipment Type: Track

Action Taken: Broken Rail - Repaired/Replaced

Suspected Reason: Equipment failure

mntr bonded rail, all operational checks performed.

Operational Checks Performed

### Incident # 5552030 Closed

**Incident History** 

**Description** 04/09/2012 00:37:54

Status Unassigned

By James Earp - Signals

Inc Type Track circuit (TOL)
Responsibility Control Center

Asset Status Dtl Responsible Dept.

Priority 1 Message#

Jumpers N/A

BALT BC Desk 5310-5311

Old Main Line EE Davis 0020/08 Lamp Indication

Old Main Line Davis-Avalon 0020/08 Track Circuit - 13 segment

Old Main Line Avalon 0020/08 Power Off

Log indicates:

23:44:09 5310 102 Lamp Out Detected (EE Davis)

23:49:43 5310 013 Track Occupied Indication 23:49:47 5311 Power Off Indication On

Updated04/09/201200:38:18StatusUnassignedBy James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

New Asset Added: 5310 - EAST END OF DAVIS

Updated 04/09/2012 00:38:36 Status Unassigned By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

New Asset Added: 5311 - WEST END OF AVALON

Updated 04/09/2012 03:15:23 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

Lamp Out Indication Off @ 01:18:09

TOL and Power Off Indication still on.

Updated 04/09/2012 04:02:38 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Maintainer is on site and making checks.

Updated 04/09/2012 04:02:53 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

Asset Removed: 5310 - EAST END OF DAVIS

Updated 04/09/2012 05:48:12 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Responsible Dept.

Responsible Dept.

Message#

Jumpers N/A

Maintainer reports broken rail within MP BAC 12.7 to 12.8. 141 lb, south rail, 1" full break on a curve. MoW notified.

Updated 04/09/2012 06:02:16 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

Asset Removed: 5311 - WEST END OF AVALON

Updated 04/09/2012 06:15:10 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

MoW ETA 07:07.

Closed 04/09/2012 14:14:13 Status Closed By Gary Bishop II - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept. Engineering

Message#

Jumpers N/A

Incident Resolved: 04/09/2012 10:30:00

Equipment Type: Track

Action Taken: Broken Rail - Repaired/Replaced

Suspected Reason: N/A

mntr reports rail had been repaired at 1030 Operational Checks Performed

# Incident # 5651933 Closed Incident History

Description 06/16/2012 17:29:01 Status Unassigned By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

ba bc om sub

tol 5310 013 on by itself, trains getting bad signals through there

Updated 06/16/2012 18:06:19 Status Escalated By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

call list exhausted. Signal supervisor notified and will handle dispatching a mntr.

Updated 06/16/2012 22:18:03 Status Escalated By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

mntrs are currently on site waiting to get track time.

Updated 06/16/2012 23:01:30 Status Escalated By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Jumpers N/A

Maintainers are still waiting to get track time.

Closed 06/17/2012 03:35:15 Status Closed By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Signals Message# Jumpers N/A

Incident Resolved: 06/17/2012 03:27:00 Equipment Type: Equipment/relays

Action Taken: Replaced

Suspected Reason: Other electrical

Maintainers changed multiple fuses and lightning arrestors at multiple locations. Unsure of the cause. No storms in area. ESS

briefed with dispatcher - not aware of any MoW equipment in the area at the time of incident.

Operational Checks Performed

### Incident # 5702380 Closed Incident History

Description 07/20/2012 00:08:35Status UnassignedBy James Earp - SignalsInc Type Track circuit (TOL)Asset Status DtlPriority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

**BAL CHIEF** 

BC DISPR OM SUB

**LOCATION 5310-013** 

**TOL BETWEEN AVALON AND DAVIS** 

Closed 07/20/2012 04:03:49 Status Closed

Inc Type Track circuit (TOL)

Asset Status Dtl

Responsibility Control Center Responsible Dept. Weather

Incident Resolved: 07/20/2012 04:03:00

Equipment Type: N/A

Action Taken: Egpt tested & fnd working as intended

Suspected Reason: Other weather

TOL off for some time now. Possibly due to storms in area.

Operational Checks Performed

Updated 07/20/2012 04:57:27 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

BAL CHIEF BC DISPR OM SUB

LOCATIONS 5310-013 AND 5311-003 2-TOL'S BETWEEN AVALON AND DAVIS

Power off indication on @ WE Avalon and TOLs approx same time.

Updated 07/20/2012 04:57:44 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

New Asset Added: 3 - 3 CKT WE AVALON TO EE DAVIS

Updated 07/20/2012 05:40:02 Status Active By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

New Asset Added: 5311 - WEST END OF AVALON

Closed 07/20/2012 13:13:27 Status Closed By Kareem Battle - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Weather Message# Jumpers N/A

Incident Resolved: 07/20/2012 12:13:00

Equipment Type: Track

Action Taken: Electronic track unit-repaired/replaced/adjusted

Suspected Reason: Other weather

mntr had to increase the track current at union dam and ellicott city. all op checks were performed

Operational Checks Performed

Incident # 5703469 Closed Incident History

**Description** 07/20/2012 15:20:49

Status Unassigned

By Travis Hudson - Signals

By Robrt Flora - Signals

Jumpers N/A

Jumpers N/A

Jumpers N/A

Priority 1

Message#

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Balt

Old Main Line Sub

BC Disp

Track lights - 5310 013.

Updated 07/20/2012 15:37:43 Status Escalated By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Perpensibility Central Center

Perpensibility Central Center

Perpensible Dept

Responsibility Control Center Responsible Dept. Message# Jumpers N/A Exhausted call list. Supervisor notified. The incident handed over to the Supervisor of the territory for further handling.

Jumpers N/A

Jumpers N/A

Updated 07/20/2012 16:29:10 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Asset Status Dtl

Responsible Dept.

Priority 1

Message#

Signal Maintainer en route.

Updated 07/20/2012 21:05:41 Status Active By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Responsibility Control Center

Responsible Dept

Message

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Signal Maintainer reports:

Going on HSL.

Trouble is between Union DAM Intermediate and Ellicott Intermediate.

Open track circuit.

Updated 07/20/2012 21:11:33 Status Escalated By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Page 2015

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Signal Supervisor reports:

Dispatcher did not give time to work.

Supervisor will handle.

Updated 07/20/2012 21:30:41 Status Escalated By Travis Hudson - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A
At location 5310 013: WB trains getting a Restricted Proceed at intermediate Ellicott City and Clears at Daniels and Union Dam.

EB trains getting Restricted Proceeds at intermediates Union Dam and Daniels and a Clear at Ellicott City.

Updated 07/20/2012 23:41:51 Status Escalated By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Broken rail at Union Dam. Maintainer Poole will brief with RM Smith.

Closed 07/21/2012 02:11:43 Status Closed By James Earp - Signals

Inc Type Track circuit (TOL)

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

Incident Resolved: 07/21/2012 02:11:00

Equipment Type: Track

Action Taken: Broken Rail - Repaired/Replaced

Suspected Reason: Other department

Maintainer bonded rail plug.
Operational Checks Performed

### Incident # 5748611 Closed Incident History

Description 08/21/2012 00:20:26 Status Unassigned By Kareem Battle - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1
Responsibility Control Center Responsible Dept. Priority 1
Jumpers N/A

Balt

Old Main Line Sub

BC Disp

U81318 EB on single main reports train in emergency. Crew inspected and reports at least one car has fallen off a bridge onto a public road - Main St. historic Ellicott City.

Updated 08/21/2012 00:20:27 Status Unassigned By Kareem Battle - Signals

Inc Type Derailment Main Track

Asset Status Dtl

Priority

Responsibility Control Center

Responsible Dept.

Priority

Message#

Jumpers N/A

Notification has been sent to the following:

Donald Hodges
Daniel Zink
James Purl
C Manager

Updated 08/21/2012 00:28:58 Status Unassigned By James Lubcke - - C and S

Inc Type Derailment Main Track Asset Status Dtl Priority 1
Responsibility Control Center Responsible Dept. Priority 1
Jumpers N/A

Left Message with Jamie Purl

Updated 08/21/2012 00:32:02 Status Unassigned By James Lubcke - -C and S

Inc Type Derailment Main Track

Asset Status Dtl

Responsibility Control Center

Responsible Dept.

Priority 1

Message#

Jumpers N/A

Chief Engineer Olson Briefed.

Updated 08/21/2012 00:41:08 Status Active By Kareem Battle - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1
Responsibility Control Center Responsible Dept. Priority 1
Jumpers N/A

Ess was unable to connect to the Daniels dd at mp bac 18.1. A mntr is headed to the location to get the info.

Updated 08/21/2012 03:40:40 Status Escalated By Kareem Battle - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

mntrs are still working on getting the dd info from mp bac 18.1 and 38.9.

Updated 08/21/2012 05:41:54 Status Escalated By Kareem Battle - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

mntr is new and currently having trouble pulling the dd logs. Ess spoke with the signal supervisor and he's working on getting the mntr some help.

Updated 08/21/2012 06:27:17 Status Escalated By Kareem Battle - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

mntr went hsl, signal supervisor will dispatch a mntr. Log have not been pulled yet.

Updated 08/21/2012 07:48:58 Status Escalated By Gary Bishop II - Signals

Inc Type Derailment Main Track

Asset Status Dtl

Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

#### Derailment Mainline Track Information:

1. Train ID - **U81318** 

2. Direction of Travel - E/B

3. Estimated Speed - undetermined

4. CADS Location - 5310

5. Milepost of Derailment - BAC 12.5

6. Timetable Speed - 25 mph

7. Number of Occupants/injuries - 3 crew members/0 injuries

8. Number of fatalities - 2 OSP fatalities

Updated 08/21/2012 08:55:13 Status Escalated By Gary Bishop II - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Message# Jumpers N/A

Signal Foreman Kennedy, Kevin is currently at Daniels DD BAC 18.1, but is having trouble with the printer.

Closed 09/05/2012 10:05:28 Status Closed By Gary Bishop II - Signals

Inc Type Derailment Main Track Asset Status Dtl Priority 1

Responsibility Control Center Responsible Dept. Engineering Message# Jumpers N/A

Incident Resolved: 08/22/2012 10:02:00

Equipment Type: Track

Action Taken: Made other repairs
Suspected Reason: Other department

No signal issues or damage, all equipment working as intended.

**Operational Checks Performed**