



Structures/Maintenance 7 - Photo 1. Accident site with gully between initial impact point and wreckage debris.