



Structures/Maintenance 7 - Photo 3. Initial impact point. Note angle formed in vegetation before initial impact point.