



Structures/Maintenance 7 - Photo 6. Fuselage and component crushing. Note: Frayed wiring.