UPPER SKIN PANEL - WING CENTER TANK

CW-124 Z-2675 GREEN

This is a portion of stringer S-16 that is burnt and bent on one end. The fasteners that remain in the stringer have failed in shear except in those areas that are noted on the sketch that have failed in tension. See the sketch for definition of the remaining stringer.

The fire and explosion group notes contain complete documentation of the fire damage and soot accumulation.

Worm Stegant 10/20/26 BOBING

50 GREEN 11/01/96 ALPA Styphen F. Klapachten Figh-11-04-96 No Photo R Gracletty JAH 11-10-96 Afflight 11-22-76

W. Styant Wedge

RBL 75:39 LIGHT SOOT RBL 57.50 CENTER SECTION UPPER STRINGER !! 886 33.99 MODERAME SOUT CW-124 Z-2675 GREEN TRG SOOTED ON SKIN/STIENGER INERFACE 785 733 FASTENCE TENSION SEVEREN DUTORIED HEAVY SOOT/BURNED 3 Stephen F. KlapacHin FAA-11-04-46 No Shote