

SIDE OF BODY RIB - RIGHT WING - WING CENTER TANK

CW-333

Z-2829

GREEN

This segment is a 26" portion of the inbd and outbd stiffeners that are common to the midspar and the side of body rib web that is sandwiched between the two stiffeners. The upper portion of the stiffener has a mating fracture with CW-803.

None of the midspar web for either the center section or the outbd wing midspar remains attached. The remaining fasteners in the holes exhibit shear failures. All of the fasteners remain intact for the fasteners that are common to both stiffeners thru the side of body rib web.

There is some soot on the fastener heads on the portion that is in the wing center section. See the fire and explosion group notes for complete documentation.

W. Stuyant 11/12/96 BAEIN4
M. Nicks 11-26-96 TWA
J. Hill 12-7-96 FAA
R. Beckett 12-7-96 JAM
SD GREEN 12-17-96 ALPA