

SWB #2 STIFFENER

R.L. WHITTINGTON  
2/20/97

CW 718 D2094 WHITE

FULL LENGTH STIFFENER AT RBL 17.2.  
STIFFENER IS BENT FWD 90° 16" FROM  
THE BOTTOM. FASTENERS THAT ARE  
COMMON TO SWB#2 MANUFACTURING DOOR  
FRACTURED IN TENSION. FASTENERS THROUGH  
THE SWB ARE FRACTURED IN SHEAR.

STIFFENER IS SOOTED.

Leigh D. Johnson - ALPA  
3-21-97

Shandukhan TWA 3/24/97

Stephen F. Klapach  
FAA-04-04-97

Dennis Santiago IAM  
4-2-97