

SWB #2 STIFFENER

R.L. WHITTINGTON
2/20/97

CW 719 D2095 WHITE

SWB #2 STIFFENER AT RBL83^①
FULL LENGTH STIFFENER FAILED THROUGH
STIFFENER WEB.

PART IS SOOTED, HAS SALT WATER
CORROSION.

① LOCATION IS APPROXIMATE

Shandshid IA 3/24/97
Stephen F. Klapach
FAA 09-0A-97

Dennis Santiago IAM
4-2-97

(
AUSA
John
3-28-97