



Structures 7 - Exhibit No. 7C - Photo 12. View of the rear fuselage and separated left wing. Note the extensive fire damage to the passenger cabin. Also note the lighting system structural support column obstructing the aft galley service door opening.