



Structures 7 - Exhibit No. 7C - Photo 14. View of the rear fuselage from beneath the runway 22L approach lighting system catwalk. Note the extensive heat damage (i.e. sagging skin) on the upper fuselage shell, forward of the rear pressure bulkhead.