



Structures 7 - Exhibit No. 7C - Photo 15. View of the left (aft) overwing emergency exit door external surface near its respective opening. Note the closed position of the external door handle and the fire damage to the leading edge and lower aft corner.