

Structures 7 - Exhibit No. 7C - Photo 2. Aerial photo of N215AA wreckage. Note the tire tracks the end of runway 4R, the breakup of the airplane, and damage to the runway 22L approach lighting system. View looking South. (Photo by J.K. Lloyd's Inc.))