



LOG # FBM - 21

TARGET # \_\_\_\_\_  
 COORD: LAT \_\_\_\_\_  
 LONG \_\_\_\_\_

DEBRIS FIELD RED  
 TAG # A139  
 (ret 12/4/96)

FLOOR ASSY STA 760 TO STA 800  
 RBL 33 RBL 72

FLOOR PANEL # 86 FWD 40" FRACTURED @ STA 800  
 CONNECTED TO RBL 54.49 S/C AND PANEL SPLITTER @  
 RBL 37.5. ALSO INCLUDE FWD 40" OF F/P # 90.

RBL 33.99 S/C ATTACHED, FRACTURED @ STA 760 AND STA 782

RBL 54.49 S/C ATTACHED, FRACTURED @ STA 760 AND STA 801

STA 760 F/B <sup>UPPER CHORD</sup> FROM RBL 46 TO RBL 72 WITH WEB  
 & STIFFENERS, (SEE F/B DWG)

STA 780 F/B UPPER & LOWER CHORDS, WEB AND STIFFENERS,  
 RBL 33 TO RBL 72 (SEE F/B DWG)

STA 800 F/B UPPER CHORD, WEB & STIFFENERS,  
 RBL 40 TO RBL 56 (SEE F/B DWG)

Dennis Santiago IAM  
 11/23/96

BARRY SMITH BOEING  
 10/21/96

Stephen F. Klupcott JR  
 FAR 10-26-96

Time being  
 10/22/96  
 [Signature]  
 10/11/96