



(VARIOUS STA 940 PIECES)
-3A

FLOOR BEAMS STA 920, & 940 UPPER CHORDS WITH SOME WEB & STIFFENER. SEE F/B BOOK

SEAT TRACK RBL 98, 58, RBL 75, 92 FROM 919 TO 940 & RBL 54, 99 FROM 935 TO 940

F/P PIECES OF # 101 (STA 900 TO 940) & # 107 STA 920 TO STA 940

-3B LOWER CHORD STA 940, LBL 40 TO RBL 34 WITH SOME WEB & STIFFENERS (SEE F/B BOOK)

-3C F/B & FRAME CONNECTION STA 940, LBL 43 TO SOB WITH FRAME S 25 TO S-28. LBL 96 STABILIZATION INTERCOSTAL ATTACHED STA 940 TO STA 960. POST FRACTURED 3" BELOW F/B. WEB IS INTACT OUTBD OF LBL 75. (SEE BOOK)

-3D F/B LOWER CHORD STA 940 LBL 70 TO LBL 40 WITH SOME WEB & STIFFENERS (SEE DIAGRAM)

-3E UPPER CHORD STA 940, RBL 12.5 TO RBL 33 WITH SOME WEB (SEE DIAGRAM)

Dennis Santiago IAM
11/23/96

Time
10/24/96

Barry Smith 10/23/96
XOU JAMES FAA
10.24.96