

LOG # LF136

TARGET # Z2882

COORD: LAT _____

LONG _____

LF136 CONSISTS OF PRESSURE

DECK FLOOR BEAM AT DEBRIS FIELD

LBL 11.33 FROM STA. 1376 TO 1410

SEAT TRACK UPPER CHORD AND CROWN IS ATTACHED FROM STA. 1378-1415. A PASSENGER SEAT REAR

LEG IS ATTACHED AT STA 1402. THE LOWER CHORD HAS FAILED IN THE RADIUS. THE FORWARD

DIAGONAL BRACE FROM THE PASSENGER SEAT IS STILL ATTACHED TO THE REAR LEG OF THE SEAT LEG.

THE BEAM WEB HAS NO SIGNIFICANT BENDING.

Robert J. Hogg

TWA 2/28/97

Dennis Santiago IAM

3-6-97

Stephen F. Klupachtz

FAM 03-14-97

Night D. John - ALPA
3-17-97

Brandon K. Hogg
TWA 3/21/97

R. Harwood 3/22/97

Boeing

5


65B1335

65B08268-1
65B13353-1
65B15483-1
65B15483-55

65B08269-1
65B13354-1
65B15484-1

FOR REWORK SEE
65B03926-1, 2
65B23976-101 THRU 108
-91, 92, 169, 4-170

FOR REWORK SEE
65B03976-1, 2
65B23978-1 THRU 12
65B23786-1, 2, 3, 4



ITEM	LOG #
A	LF16B *
B	RF126 *
C	LF135 *
D	LF136
E	LF119 *

UP
FWD
SCALE: NONE

LBL 11.33
FLRBM

* PART OF

5/24/97 10:00 AM
1-200-0374-47