Right Body Gear Doors

LG9 Log Number **Debris** Field Green Z3328, Z2746, Z3064, Z3355 Target Numbers Coordinates: Latitude Longitude

Outboard Forward Door (Z3328)

Outboard hinges attached to fuselage structure which is approximately 17 inches circumferentially x 130 inches fore-aft.

Outer skin dented and cracked along leading edge of dent adjacent to second rib aft of leading edge.

Rod failed 1.5 inches from door fitting.

Structure has minor surface abrasions. No visible indication of soot.

Inboard Forward Door (Z2746)

Inner skin has cracking and a dent as shown on illustration.

Outboard hinges failed.

Inboard and outboard sections of leading edge door seals not attached.

Rod not attached.

Structure has minor surface abrasions. No visible signs of soot.

Inboard Aft Door (aft segment Z3064, forward segment Z3355)

Numerous punctures, cracks, and skin flapping exists. See illustration.

Aft hinge location has fuselage fitting attached.

Second hinge forward failed.

Third hinge forward is attached to outer skin.

Aft segment of door is separate from forward segment.

A mangled segment of forward edge approximately eleven inches by four inches is not attached.

Structure has minor surface abrasions. No visible indication of soot.

Outboard Aft Door

Not attached to door assembly. Door has not been identified.

TWA-REPHLD Apples 11-20-96 Stephen 1- Klupuchon FIM 12-06-96

SD GREEN ALVY 01-20-97 R. Scachitty 12-696 JAM D. Outle 12/18/96 BUEING



