




LW 18  
 Green Area C203Z  
 Received 8-19-96 Lot B

Wing Skin Segment  
 Lower Left Panel



- Mid Spar splice chord is missing inboard of WS 701. The remaining chord has no vertical flange
- Fracture surfaces are not sooted
- No evidence of fatigue failure
- Strut fitting is not attached

10/13  
 Stephen F. Powers - TWA  
 Powers - FAA  
 Jim Powers  
 8/28/96 - BOEING

11/2/96 - ALPA  
 11-5-96 - IAM  
 D. Santiago - NTSB