



Structures 7 - Photo 10. Close-up view of right wing  
Note: fractured stringers bent upwards