



Structures 7 - Photo 14. View of burned outboard section of right horizontal stabilizer