



Structures 7 - Photo 19. View of fractured right landing gear trapezoidal panel