



Structures 7 - Photo 4. View of the empennage and damaged outboard end of the left horizontal stabilizer