



Structures 7 - Photo 6. View of the No. 3 (right) engine  
Note: engine tail cone is crushed and the engine inlet case is destroyed