



Structures 7 - Photo. 11 - View of fractured inboard right wing root at side of body.