



Structures 7 - Photo. 12 - View of upper rear spar cap fracture face at inboard right wing root side of body.