



Structures 7 - Photo. 5 - View of the fractured lower right winglet attach fittings