

upper fasterners for the outboard flap hinge. Note the opposite direction of fractures.