



Structures 7 - Photo. 8 - View of the fractures flap hinge inboard side brace fitting.