LOG # EA RFI -RIGHT SDE TARGET # 2686, 7P COORD: LAT 40° 38' 41.2" LONG 072° 3 15.2" 400H SEE ADDITIONAL COMMENTS RÐ DEBRIS FIELD PORTION of FUSELAGE RIGHT HAND STATION 760-960, STR 22 - STR 37 LOWER EDGE BENT OUTWARD IN VARIED DEGREE AFT LOWER POLDED BACK ON ITSELF. F HAS TIGHT SPIRAL AFT END & PANEL ON UPPER 1/3 COILING A TO STA 900 TO 960 574 780 70 FLOOR BEAMS BROKEN AT POSTS STA 900. FRAMES EXTEND FROM 5-25 TO Only a portion of floor learn structure, remained attached 5-36 from the Outerskin inboard. Section of floor beam between STA 820 & 840 was ensited down. There was no evidence af any fire damage to the port of Shutter REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

REFER METALLURGY GROUP NOTES

Dennis Santiago I AM 10/120196

BARRY SMITH - Boeing

Shrancherdent TwoA 10/9/96 B Some 10/22/96 TOFAA 10-10-96 SF(FAA)









