


LOG # RF 141
 TARGET # Z 2739
 COORD: LAT _____
 LONG _____

RF 141 CONSISTS OF PRESSURE DEBRIS FIELD GABBN
 DECK FLOOR BEAM AND PART OF A CABIN SEAT LEG. THE LOWER CHORD HAS FAILED IN THE RADIUS AND THE UPPER CHORD HAS FAILED ALONG MOST OF THE LENGTH OF THE SECTION. THIS SECTION IS AT RBL 75.92 FROM BS1447 TO 1480.

Robert S. Steger
 TWA 2-28-97



LOWER CHORD FRACTURED AT RADIUS
 R. Hanover 3/28/97
 Boeing

Stephen F. Klepach Jr
 FAA - 03-05-97

Dennis Hartings IAM
 3-7-97

Leigh D. Johnson
 3-17-97


658133(55

65808268-1
65813353-1
65815483-1
65815483-55

65808269-1
65813354-1
65815484-1

FOR REWORK SEE
65823926-1, 2
65823978-101 THRU 108
-91, 92, 169, 4-170


FOR REWORK SEE
65823978-1, 2
65823978-101 THRU 108
-91, 92, 169, 4-170



Stephen F. Klipsch
FSA 03-05-47

FOR REWORK SEE
65823978-1, 2
65823978-101 THRU 108
65824706-1, 2, 3, 4

C3



SCALE: NONE

ITEM	LOG #
A	RF 126 *
B	RF 126 *
C	RF 141

RBL 75.92
FLR BM

* PART OF