

RF 181
 LOT NO. 8-3-96-45
 RF 182
 LOT NO. 8-4-96-65

BS 320

BS 300

NW Sidewall
 Attach

UPPER AREA
 BENT 0B
 30-45°

RF 181

SLIGHT
 DAMAGE AT
 FWD AND AFT ENDS

STIFFENER

AREA ABOVE
 AND BELOW
 SLIGHTLY BENT
 0B

S-41R

AREA BELOW
 BENT SLIGHTLY
 1B

STIFFENER

REMAINS
 ATTACHED TO
 RF 182 AND
 HAS NEGLIGIBLE
 DAMAGE

RF 182

- S-40R

UPPER
 AREA
 BENT 90°
 0B

[Signature]
 9-10-97

Dennis Santiago IAM
 9-12-97

TWA

[Signature]
 9-11-97

Tom Tochner
 FAA 9-11-97

S. Chasidua
 BOEING 9/12/97