

LOG # RF-22

TARGET # _____

COORD: LAT _____

LONG _____

STA 1480-1580

STR 19R-26R

ON RIGHT HAND SIDE

DEBRIS FIELD

NOT

AVAILABLE

~~NO TAG~~

C2334

REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE

*Missing from
10-11-96
Tom Toland
FAA 10-11-96*


*Dennis Santiago IAM
10/14/96*

SKFAM


*Robert Hancock
8/12/96 2*

RF-22

4½ WINDOW SEGMENT AFT OF STA 1480
STA 1480 - 1580, STR 19R - 26R




- MOST FRACTURE SURFACES ARE 'ANGLED' (BUT LIGHT SOOT ON THE OUTSIDE)
- NO SIGN OF HEAT DAMAGE, WHITE PAINT ON EXTERIOR IS NOW LIGHT GREY. ½ OF RED PAINT BELOW WINDOWS HAS PEELED OFF



R Hanover
e/12/90

3



RF22
 RA
 elizaco
 4