


REFER FIRE AND EXPLOSION GROUP NOTES FOR FIRE DAMAGE



This SECTION OF RIGHT FUSE LAGE SKIN MEASURES APPROX 2'x 31/2' AND ENCOMPASSES FRAME STATIONS 1080 THRU 1120, AND STRINGERS S24R THRU 527R. The piece is irregular in shape and is Torn and sheaped on All addes, Many places where river Heats Had bean, And BNIY holes exist NOW, STRINGERS FOR The most part are missing, only SMALL SECTION OF STRINGERS FOR THE MOST PART ARE MISSING, ONLY hetween STA 1080 +1100, AND STRINGERS 527 HETWEEN STA 1080 +1100, AND STRINGERS 527

EXTERIOR SURFACE OF FUSEIAGE SKIN (PAINTED RED) COVERED WITH Black SOOT, AND PAINT PEELED IN SOME SPOTS. .... Quill

Dennis Sontiago IAM

bluanduhida TWA 500 Due of you

Lou Zehlund 8/15/96 **2**