



Structures 7A - Photo 10. Damage to middle hinges of left forward cowling doors.