

NATIONAL TRANSPORTATION SAFETY BOARD

Office of Aviation Safety Washington, D.C. 20594

May 3, 2017

STRUCTURES GROUP

Factual Report ERA17FA066

Appendix A – Figures (8 pages)




Figure 1 – Fairchild SA-227AC airplane



Figure 2 – Accident airplane, N765FA




Figure 3 – SA-227AC Fuselage Station diagram




Figure 4 – SA-227AC Fuselage Stringer diagram




Figure 5 – SA-227AC Wing Station diagram




Figure 6 – SA-227AC Vertical Stabilizer and Rudder Station diagram




Figure 7 – SA-227AC Horizontal Stabilizer Station diagram



Figure 8 – Wreckage map, N765FA



Figure 9 – Concentrated area of wreckage, N765FA



Figure 10 – Left fuselage damage



Figure 11 – Right fuselage damage oriented diagonally



Figure 12 – Vertical stabilizer and rudder damage

8